Editorial changes to create Printer MIB version 7.

1. para 2.2.13.1 "(3) Alert codes are reported…" was "(3) Alert codes reported…"
   This is issue 4.

2. Added "other(1), unknown(2), items(18), percent(19)" to PrtCapacityUnitTC.

3. Added "other(1), unknown(2), percent(19)" to PrtMarkerSuppliesSupplyUnitTC.

4. Removed spaces between name and enum value in PrtConsoleDisableTC.

5. Removed "gb" from prtLocalizationLanguage. (not a language)

6. Added "GB" to prtLocalizationCountry.

7. Added a space between the OBJECT-TYPE value and the closing brace in
   prtMarkerCounterUnit.

8. Added a space between the OBJECT-TYPE value and the closing brace in
   prtAlertCode.

9. Added "size 3.875 by 8.875" to na-number-9-envelope in Appendix B and C.

10. "iso-a10-white" was "iso-10-white"   (a typographic error from RFC 1759)

Note: I did not increase the size specification for prtLocalizationLanguage as a result of
the comments that we received from the ADs.

     Ron Bergman
     March 19, 2001